

Atmospheric Pressure

3b

TECHNICAL HELP

The information contained in this document is offered for assistance in the application of our products, but it does not constitute a warranty of merchantability or fitness for any particular purpose.

Glazing Solutions



Twineseal Limited

Unit 20, Green Park Business Centre
Sutton On Forest, York, YO61 1ET
Tel 01347 811773 Fax 01347 811774



Spacer Deflection into IG Units

For some time investigations into the possible causes of the phenomenon exhibited by some double glazed units where the spacer has ingressed into the unit on the longer sides has been examined. This has the effect of taking the hot melt sealant with it. The spacer bends, permanently deforms and is prevented from returning to its original position. The ingress was such that it can project beyond the sightline. It should be stressed that these units have not failed in conventional terms but the visual appearance was obviously unacceptable.

There appears to be a distinct type of unit that is prone to occasionally exhibiting this effect, namely units with a high aspect ratio and typically opening light units. It is important to understand the forces and processes occurring within an installed unit. When units are installed, they undergo differing degrees of expansion and contraction depending on levels of exposure and the direction of exposure. With high aspect ratio units, the narrowness of height will prevent the glass from deflecting fully when the unit is exposed to heat from direct sunlight. Also the desiccant may possibly desorb nitrogen that would change the original negative pressure into a positive pressure. At the same time, in prolonged sunlight, the spacer and sealant will also warm, progressively softening the sealant the higher the temperature reached. Temperatures commonly in excess of 60⁰ and as high as 90⁰ Centigrade have been measured inside units subjected to prolonged sunshine. When the glass and airspace subsequently cool down, the sealant will remain soft and pliable for a slightly longer time. The "negative pressure" will then return because of the contraction of the air and possible re-adsorption of the nitrogen. The spacer bar, with the still softened sealant could then be pulled inwards. When the sealant cools, the spacer is "trapped" in its new position. This effect is thought to be caused by cyclic heating and movements that occur over a long period.

Document Supplied by
CEN Solutions Limited
Unit 3 Penkrige Industrial Estate, Boscomoor Lane,
Penkrige, Staffordshire ST19 5NZ